

JAPANESE VEHICLE AUCTION INSPECTION SHEET

Generic demonstration layout for website education - not issued by any auction house

SAMPLE REPORT

AUCTION & VEHICLE INFORMATION			
Lot No.	S-32045	Chassis	TRJ150-01XXXXXX
Auction Date	15 Oct 2026	Engine	2,700 cc Petrol
Make	Toyota	Transmission	Automatic
Model	Land Cruiser Prado	Drive	4WD
Variant	TX L Package / 7 Seater	Color	Pearl White / 070
Model Year	2021	Mileage	34,256 km

AUCTION GRADE
4.5
Overall Grade
Interior: B

EQUIPMENT / OPTIONS		
☒ Sunroof	☒ Leather Seats	☒ Navigation / TV
☒ Back Camera	☒ Power Steering	☒ Power Windows
☒ ABS	☒ Airbags	☒ Smart Key
☒ Alloy Wheels	☒ Climate A/C	☒ 7 Seats

SALE POINTS
- Modellista-style aero kit - One owner indicated - Spare key noted - Service record available

INSPECTOR REMARKS
- Seat wrinkles / light wear - Minor interior soiling - Underbody surface rust noted - Small scratches / dents - Front bumper: A1 - Right rear door: U1 - Rear panel: W2 - No major structural repair noted on sheet

BODY CONDITION DIAGRAM

AUCTION REPORT - ENGLISH TRANSLATION SUMMARY

Reference guide explaining the information commonly found on Japanese auction sheets

SAMPLE REPORT

VEHICLE SUMMARY

Make / Model	Toyota Land Cruiser Prado	Variant	TX L Package (7 Seater)
Year	2021	Engine	2.7L Petrol
Transmission	Automatic	Drive	4WD
Mileage	34,256 km	Exterior	Pearl White (070)
Auction Grade	4.5	Interior Grade	B
Chassis	TRJ150-01XXXXXX	Lot Number	S-32045

TYPICAL AUCTION GRADE GUIDE (GENERAL REFERENCE)

5 / 6 / S	Very high / near-new condition	3.5	Average used condition
4.5	Very good used condition	3	More visible wear / repairs
4	Good condition; minor imperfections	R / RA	Repair / accident history designation

COMMON BODY / CONDITION CODES

A1 / A2 / A3	Scratch - increasing severity	U1 / U2 / U3	Dent - increasing severity
W1 / W2 / W3	Repair / repaint waviness	S1 / S2	Rust
C1 / C2	Corrosion	X	Panel requires replacement
XX	Panel replaced	B1 / B2	Dent with scratch / larger damage
P	Paint issue	G	Stone chip / glass mark
Y	Crack / tear depending on area	R / RA	Vehicle auction grade indicating repair history

Important for buyers

Auction grades and condition codes can vary slightly by auction house. Always verify the original sheet against the chassis number, lot number, auction date and available auction-house records. Translation summaries should be treated as an aid, not a substitute for the original auction sheet or an independent physical inspection of the vehicle.